



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Thursday 19th December, 2013

Dear Customer,

Re: Product Change Notification for Harwin product.

As part of our continuous improvement process, please be advised that the following ranges of Datamate L-Tek SMT are now being manufactured with a different plastic material:

- M80-665
- M80-666
- M80-667
- M80-826
- M80-827
- M80-828
- M80-835
- M80-836
- M80-837
- M80-926
- M80-927
- M80-928

Please see the attached spreadsheet for a complete list of affected items.

The plastic material used on these connectors was a grade of 30% Glass-filled Polyamide 46. We are now using a grade of 30% Glass-filled PPS. This change will not affect the dimensions, electrical or mechanical performance, or appearance of the connectors. The same PPS material is already used on the J-Tek versions of Datamate.

Stocks of the most popular products are now shipping in PPS, and other lines will convert during the next few months. If you need to confirm which material you have been shipped, please advise the part number and batch number to our Customer Services Team on sales@harwin.co.uk, and they will confirm this information.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

Product Change Notification from Harwin

Part number affected	Drawing showing new material
M80-6650422	M80-665.pdf
M80-6650442	M80-665.pdf
M80-6650445	M80-665.pdf
M80-6650622	M80-665.pdf
M80-6650642	M80-665.pdf
M80-6650645	M80-665.pdf
M80-6650822	M80-665.pdf
M80-6650842	M80-665.pdf
M80-6650845	M80-665.pdf
M80-6651022	M80-665.pdf
M80-6651042	M80-665.pdf
M80-6651045	M80-665.pdf
M80-6651222	M80-665.pdf
M80-6651242	M80-665.pdf
M80-6651245	M80-665.pdf
M80-6651422	M80-665.pdf
M80-6651442	M80-665.pdf
M80-6651445	M80-665.pdf
M80-6651622	M80-665.pdf
M80-6651642	M80-665.pdf
M80-6651645	M80-665.pdf
M80-6651822	M80-665.pdf
M80-6651842	M80-665.pdf
M80-6651845	M80-665.pdf
M80-6652022	M80-665.pdf
M80-6652042	M80-665.pdf
M80-6652045	M80-665.pdf
M80-6652622	M80-665.pdf
M80-6652642	M80-665.pdf
M80-6652645	M80-665.pdf
M80-6653422	M80-665.pdf
M80-6653442	M80-665.pdf
M80-6653445	M80-665.pdf
M80-6654422	M80-665.pdf
M80-6654442	M80-665.pdf
M80-6654445	M80-665.pdf
M80-6660422	M80-666.pdf
M80-6660442	M80-666.pdf
M80-6660445	M80-666.pdf
M80-6660622	M80-666.pdf
M80-6660642	M80-666.pdf
M80-6660645	M80-666.pdf
M80-6660822	M80-666.pdf
M80-6660842	M80-666.pdf
M80-6660845	M80-666.pdf
M80-6661022	M80-666.pdf
M80-6661042	M80-666.pdf
M80-6661045	M80-666.pdf
M80-6661222	M80-666.pdf
M80-6661242	M80-666.pdf
M80-6661245	M80-666.pdf
M80-6661422	M80-666.pdf
M80-6661442	M80-666.pdf
M80-6661445	M80-666.pdf
M80-6661622	M80-666.pdf
M80-6661642	M80-666.pdf
M80-6661645	M80-666.pdf
M80-6661822	M80-666.pdf
M80-6661842	M80-666.pdf
M80-6661845	M80-666.pdf
M80-6662022	M80-666.pdf
M80-6662042	M80-666.pdf
M80-6662045	M80-666.pdf

Product Change Notification from Harwin

Part number affected	Drawing showing new material
M80-6662622	M80-666.pdf
M80-6662642	M80-666.pdf
M80-6662645	M80-666.pdf
M80-6663422	M80-666.pdf
M80-6663442	M80-666.pdf
M80-6663445	M80-666.pdf
M80-6664422	M80-666.pdf
M80-6664442	M80-666.pdf
M80-6664445	M80-666.pdf
M80-6670422	M80-667.pdf
M80-6670442	M80-667.pdf
M80-6670445	M80-667.pdf
M80-6670622	M80-667.pdf
M80-6670642	M80-667.pdf
M80-6670645	M80-667.pdf
M80-6670822	M80-667.pdf
M80-6670842	M80-667.pdf
M80-6670845	M80-667.pdf
M80-6671022	M80-667.pdf
M80-6671042	M80-667.pdf
M80-6671045	M80-667.pdf
M80-6671222	M80-667.pdf
M80-6671242	M80-667.pdf
M80-6671245	M80-667.pdf
M80-6671422	M80-667.pdf
M80-6671442	M80-667.pdf
M80-6671445	M80-667.pdf
M80-6671622	M80-667.pdf
M80-6671642	M80-667.pdf
M80-6671645	M80-667.pdf
M80-6671822	M80-667.pdf
M80-6671842	M80-667.pdf
M80-6671845	M80-667.pdf
M80-6672022	M80-667.pdf
M80-6672042	M80-667.pdf
M80-6672045	M80-667.pdf
M80-6672622	M80-667.pdf
M80-6672642	M80-667.pdf
M80-6672645	M80-667.pdf
M80-6673422	M80-667.pdf
M80-6673442	M80-667.pdf
M80-6673445	M80-667.pdf
M80-6674422	M80-667.pdf
M80-6674442	M80-667.pdf
M80-6674445	M80-667.pdf
M80-8260422	M80-826.pdf
M80-8260442	M80-826.pdf
M80-8260445	M80-826.pdf
M80-8260622	M80-826.pdf
M80-8260642	M80-826.pdf
M80-8260645	M80-826.pdf
M80-8260822	M80-826.pdf
M80-8260842	M80-826.pdf
M80-8260845	M80-826.pdf
M80-8261022	M80-826.pdf
M80-8261042	M80-826.pdf
M80-8261045	M80-826.pdf
M80-8261222	M80-826.pdf
M80-8261242	M80-826.pdf
M80-8261245	M80-826.pdf
M80-8261422	M80-826.pdf
M80-8261442	M80-826.pdf
M80-8261445	M80-826.pdf

Product Change Notification from Harwin

Part number affected	Drawing showing new material
M80-8261622	M80-826.pdf
M80-8261642	M80-826.pdf
M80-8261645	M80-826.pdf
M80-8261822	M80-826.pdf
M80-8261842	M80-826.pdf
M80-8261845	M80-826.pdf
M80-8262022	M80-826.pdf
M80-8262042	M80-826.pdf
M80-8262045	M80-826.pdf
M80-8262622	M80-826.pdf
M80-8262642	M80-826.pdf
M80-8262645	M80-826.pdf
M80-8263422	M80-826.pdf
M80-8263442	M80-826.pdf
M80-8263445	M80-826.pdf
M80-8264422	M80-826.pdf
M80-8264442	M80-826.pdf
M80-8264445	M80-826.pdf
M80-8260422P	M80-826P.pdf
M80-8260442P	M80-826P.pdf
M80-8260445P	M80-826P.pdf
M80-8260622P	M80-826P.pdf
M80-8260642P	M80-826P.pdf
M80-8260645P	M80-826P.pdf
M80-8260822P	M80-826P.pdf
M80-8260842P	M80-826P.pdf
M80-8260845P	M80-826P.pdf
M80-8261022P	M80-826P.pdf
M80-8261042P	M80-826P.pdf
M80-8261045P	M80-826P.pdf
M80-8261222P	M80-826P.pdf
M80-8261242P	M80-826P.pdf
M80-8261245P	M80-826P.pdf
M80-8261422P	M80-826P.pdf
M80-8261442P	M80-826P.pdf
M80-8261445P	M80-826P.pdf
M80-8261622P	M80-826P.pdf
M80-8261642P	M80-826P.pdf
M80-8261645P	M80-826P.pdf
M80-8261822P	M80-826P.pdf
M80-8261842P	M80-826P.pdf
M80-8261845P	M80-826P.pdf
M80-8262022P	M80-826P.pdf
M80-8262042P	M80-826P.pdf
M80-8262045P	M80-826P.pdf
M80-8262622P	M80-826P.pdf
M80-8262642P	M80-826P.pdf
M80-8262645P	M80-826P.pdf
M80-8263422P	M80-826P.pdf
M80-8263442P	M80-826P.pdf
M80-8263445P	M80-826P.pdf
M80-8264422P	M80-826P.pdf
M80-8264442P	M80-826P.pdf
M80-8264445P	M80-826P.pdf
M80-8270422	M80-827.pdf
M80-8270442	M80-827.pdf
M80-8270445	M80-827.pdf
M80-8270622	M80-827.pdf
M80-8270642	M80-827.pdf
M80-8270645	M80-827.pdf
M80-8270822	M80-827.pdf
M80-8270842	M80-827.pdf
M80-8270845	M80-827.pdf

Product Change Notification from Harwin

Part number affected	Drawing showing new material
M80-8271022	M80-827.pdf
M80-8271042	M80-827.pdf
M80-8271045	M80-827.pdf
M80-8271222	M80-827.pdf
M80-8271242	M80-827.pdf
M80-8271245	M80-827.pdf
M80-8271422	M80-827.pdf
M80-8271442	M80-827.pdf
M80-8271445	M80-827.pdf
M80-8271622	M80-827.pdf
M80-8271642	M80-827.pdf
M80-8271645	M80-827.pdf
M80-8271822	M80-827.pdf
M80-8271842	M80-827.pdf
M80-8271845	M80-827.pdf
M80-8272022	M80-827.pdf
M80-8272042	M80-827.pdf
M80-8272045	M80-827.pdf
M80-8272622	M80-827.pdf
M80-8272642	M80-827.pdf
M80-8272645	M80-827.pdf
M80-8273422	M80-827.pdf
M80-8273442	M80-827.pdf
M80-8273445	M80-827.pdf
M80-8274422	M80-827.pdf
M80-8274442	M80-827.pdf
M80-8274445	M80-827.pdf
M80-8270422P	M80-827P.pdf
M80-8270442P	M80-827P.pdf
M80-8270445P	M80-827P.pdf
M80-8270622P	M80-827P.pdf
M80-8270642P	M80-827P.pdf
M80-8270645P	M80-827P.pdf
M80-8270822P	M80-827P.pdf
M80-8270842P	M80-827P.pdf
M80-8270845P	M80-827P.pdf
M80-8271022P	M80-827P.pdf
M80-8271042P	M80-827P.pdf
M80-8271045P	M80-827P.pdf
M80-8271222P	M80-827P.pdf
M80-8271242P	M80-827P.pdf
M80-8271245P	M80-827P.pdf
M80-8271422P	M80-827P.pdf
M80-8271442P	M80-827P.pdf
M80-8271445P	M80-827P.pdf
M80-8271622P	M80-827P.pdf
M80-8271642P	M80-827P.pdf
M80-8271645P	M80-827P.pdf
M80-8271822P	M80-827P.pdf
M80-8271842P	M80-827P.pdf
M80-8271845P	M80-827P.pdf
M80-8272022P	M80-827P.pdf
M80-8272042P	M80-827P.pdf
M80-8272045P	M80-827P.pdf
M80-8272622P	M80-827P.pdf
M80-8272642P	M80-827P.pdf
M80-8272645P	M80-827P.pdf
M80-8273422P	M80-827P.pdf
M80-8273442P	M80-827P.pdf
M80-8273445P	M80-827P.pdf
M80-8274422P	M80-827P.pdf
M80-8274442P	M80-827P.pdf
M80-8274445P	M80-827P.pdf

Product Change Notification from Harwin

Part number affected	Drawing showing new material
M80-8280422	M80-828.pdf
M80-8280442	M80-828.pdf
M80-8280445	M80-828.pdf
M80-8280622	M80-828.pdf
M80-8280642	M80-828.pdf
M80-8280645	M80-828.pdf
M80-8280822	M80-828.pdf
M80-8280842	M80-828.pdf
M80-8280845	M80-828.pdf
M80-8281022	M80-828.pdf
M80-8281042	M80-828.pdf
M80-8281045	M80-828.pdf
M80-8281222	M80-828.pdf
M80-8281242	M80-828.pdf
M80-8281245	M80-828.pdf
M80-8281422	M80-828.pdf
M80-8281442	M80-828.pdf
M80-8281445	M80-828.pdf
M80-8281622	M80-828.pdf
M80-8281642	M80-828.pdf
M80-8281645	M80-828.pdf
M80-8281822	M80-828.pdf
M80-8281842	M80-828.pdf
M80-8281845	M80-828.pdf
M80-8282022	M80-828.pdf
M80-8282042	M80-828.pdf
M80-8282045	M80-828.pdf
M80-8282622	M80-828.pdf
M80-8282642	M80-828.pdf
M80-8282645	M80-828.pdf
M80-8283422	M80-828.pdf
M80-8283442	M80-828.pdf
M80-8283445	M80-828.pdf
M80-8284422	M80-828.pdf
M80-8284442	M80-828.pdf
M80-8284445	M80-828.pdf
M80-8280422P	M80-828P.pdf
M80-8280442P	M80-828P.pdf
M80-8280445P	M80-828P.pdf
M80-8280622P	M80-828P.pdf
M80-8280642P	M80-828P.pdf
M80-8280645P	M80-828P.pdf
M80-8280822P	M80-828P.pdf
M80-8280842P	M80-828P.pdf
M80-8280845P	M80-828P.pdf
M80-8281022P	M80-828P.pdf
M80-8281042P	M80-828P.pdf
M80-8281045P	M80-828P.pdf
M80-8281222P	M80-828P.pdf
M80-8281242P	M80-828P.pdf
M80-8281245P	M80-828P.pdf
M80-8281422P	M80-828P.pdf
M80-8281442P	M80-828P.pdf
M80-8281445P	M80-828P.pdf
M80-8281622P	M80-828P.pdf
M80-8281642P	M80-828P.pdf
M80-8281645P	M80-828P.pdf
M80-8281822P	M80-828P.pdf
M80-8281842P	M80-828P.pdf
M80-8281845P	M80-828P.pdf
M80-8282022P	M80-828P.pdf
M80-8282042P	M80-828P.pdf
M80-8282045P	M80-828P.pdf

Product Change Notification from Harwin

Part number affected	Drawing showing new material
M80-8282622P	M80-828P.pdf
M80-8282642P	M80-828P.pdf
M80-8282645P	M80-828P.pdf
M80-8283422P	M80-828P.pdf
M80-8283442P	M80-828P.pdf
M80-8283445P	M80-828P.pdf
M80-8284422P	M80-828P.pdf
M80-8284442P	M80-828P.pdf
M80-8284445P	M80-828P.pdf
M80-8350222	M80-835.pdf
M80-8350242	M80-835.pdf
M80-8350245	M80-835.pdf
M80-8350322	M80-835.pdf
M80-8350342	M80-835.pdf
M80-8350345	M80-835.pdf
M80-8350422	M80-835.pdf
M80-8350442	M80-835.pdf
M80-8350445	M80-835.pdf
M80-8350522	M80-835.pdf
M80-8350542	M80-835.pdf
M80-8350545	M80-835.pdf
M80-8350622	M80-835.pdf
M80-8350642	M80-835.pdf
M80-8350645	M80-835.pdf
M80-8350722	M80-835.pdf
M80-8350742	M80-835.pdf
M80-8350745	M80-835.pdf
M80-8351722	M80-835.pdf
M80-8351742	M80-835.pdf
M80-8351745	M80-835.pdf
M80-8352222	M80-835.pdf
M80-8352242	M80-835.pdf
M80-8352245	M80-835.pdf
M80-8360222	M80-836.pdf
M80-8360242	M80-836.pdf
M80-8360245	M80-836.pdf
M80-8360322	M80-836.pdf
M80-8360342	M80-836.pdf
M80-8360345	M80-836.pdf
M80-8360422	M80-836.pdf
M80-8360442	M80-836.pdf
M80-8360445	M80-836.pdf
M80-8360522	M80-836.pdf
M80-8360542	M80-836.pdf
M80-8360545	M80-836.pdf
M80-8360622	M80-836.pdf
M80-8360642	M80-836.pdf
M80-8360645	M80-836.pdf
M80-8360722	M80-836.pdf
M80-8360742	M80-836.pdf
M80-8360745	M80-836.pdf
M80-8361722	M80-836.pdf
M80-8361742	M80-836.pdf
M80-8361745	M80-836.pdf
M80-8362222	M80-836.pdf
M80-8362242	M80-836.pdf
M80-8362245	M80-836.pdf
M80-8370222	M80-837.pdf
M80-8370242	M80-837.pdf
M80-8370245	M80-837.pdf
M80-8370322	M80-837.pdf
M80-8370342	M80-837.pdf
M80-8370345	M80-837.pdf

Product Change Notification from Harwin

Part number affected	Drawing showing new material
M80-8370422	M80-837.pdf
M80-8370442	M80-837.pdf
M80-8370445	M80-837.pdf
M80-8370522	M80-837.pdf
M80-8370542	M80-837.pdf
M80-8370545	M80-837.pdf
M80-8370622	M80-837.pdf
M80-8370642	M80-837.pdf
M80-8370645	M80-837.pdf
M80-8370722	M80-837.pdf
M80-8370742	M80-837.pdf
M80-8370745	M80-837.pdf
M80-8371722	M80-837.pdf
M80-8371742	M80-837.pdf
M80-8371745	M80-837.pdf
M80-8372222	M80-837.pdf
M80-8372242	M80-837.pdf
M80-8372245	M80-837.pdf
M80-8370242R	M80-837R.pdf
M80-9260322	M80-926.pdf
M80-9260342	M80-926.pdf
M80-9260345	M80-926.pdf
M80-9260422	M80-926.pdf
M80-9260442	M80-926.pdf
M80-9260445	M80-926.pdf
M80-9260522	M80-926.pdf
M80-9260542	M80-926.pdf
M80-9260545	M80-926.pdf
M80-9260622	M80-926.pdf
M80-9260642	M80-926.pdf
M80-9260645	M80-926.pdf
M80-9260722	M80-926.pdf
M80-9260742	M80-926.pdf
M80-9260745	M80-926.pdf
M80-9261722	M80-926.pdf
M80-9261742	M80-926.pdf
M80-9261745	M80-926.pdf
M80-9262222	M80-926.pdf
M80-9262242	M80-926.pdf
M80-9262245	M80-926.pdf
M80-9270322	M80-927.pdf
M80-9270342	M80-927.pdf
M80-9270345	M80-927.pdf
M80-9270422	M80-927.pdf
M80-9270442	M80-927.pdf
M80-9270445	M80-927.pdf
M80-9270522	M80-927.pdf
M80-9270542	M80-927.pdf
M80-9270545	M80-927.pdf
M80-9270622	M80-927.pdf
M80-9270642	M80-927.pdf
M80-9270645	M80-927.pdf
M80-9270722	M80-927.pdf
M80-9270742	M80-927.pdf
M80-9270745	M80-927.pdf
M80-9271722	M80-927.pdf
M80-9271742	M80-927.pdf
M80-9271745	M80-927.pdf
M80-9272222	M80-927.pdf
M80-9272242	M80-927.pdf
M80-9272245	M80-927.pdf
M80-9280322	M80-928.pdf
M80-9280342	M80-928.pdf

Product Change Notification from Harwin

Part number affected	Drawing showing new material
M80-9280345	M80-928.pdf
M80-9280422	M80-928.pdf
M80-9280442	M80-928.pdf
M80-9280445	M80-928.pdf
M80-9280522	M80-928.pdf
M80-9280542	M80-928.pdf
M80-9280545	M80-928.pdf
M80-9280622	M80-928.pdf
M80-9280642	M80-928.pdf
M80-9280645	M80-928.pdf
M80-9280722	M80-928.pdf
M80-9280742	M80-928.pdf
M80-9280745	M80-928.pdf
M80-9281722	M80-928.pdf
M80-9281742	M80-928.pdf
M80-9281745	M80-928.pdf
M80-9282222	M80-928.pdf
M80-9282242	M80-928.pdf
M80-9282245	M80-928.pdf